

Docket No. SA-537

Exhibit No. 6-AD

NATIONAL TRANSPORTATION SAFETY BOARD

Washington, D.C.

SFFD Rescue 10 Repair Work Order

(1 Page)

WO #
31244



Equipment
72500210

Company	Department
Name: City and County of San Francisco Airport Auto Shop Address: San Francisco International Airport Building 682 City: San Francisco State: CA Zip: 94128	Number: SFFD Acct. #: Name: Fire Department Contact: Phone #: () -
Equipment	Work Order
Number: 72500210 Vin #: 10TGKAL13AS124980 Year: 2010 Make: OSHKOSH Model: STRIKER 4500 Location: Plate: Function: Driver: Acct. #: TRUK-72500210	W.O. #: 31244 Date: 07/12/2013 P.O. #: Status: Completed Assigned To: WO Location:

Comments

Job Code: 96-000 Name: Fire Truck Status: Completed Source Vehicle Condition Report PO Invoice Mechanic: 024 - Christian Pearson Date 07/12/2013 Meters 4158 Miles 846 Hours					
Item	Description	Quantity	Units	Price	Total
Labor	Christian Pearson	4.000	Hours	46.5600	186.24
Parts : 2FW243	Socket & lamp- Oshkosh	2.000	Each	1.7800	3.56
Parts : 3988155	Nozzle-piercing w/ chrome tip-	1.000	Each	2970.0000	2970.00
Parts : 4007038	Tube- pierce ext- Oshkosh	1.000	Each	232.2300	232.23
Parts : 3988199	Pipe- piercing tip 44.0 RED- O	1.000	Each	645.1900	645.19

Comments

DM: REPAIR BROKEN PIERCING TIP

cp 7-12-2013 Install new 4 piece piercing tip to replace broken one, extract broken bolts from hydraulic actuator, install 6 new socket head bolts and torque to specs. Spray lube inner boom, replace missing bolt on waterway pipe clamp, tighten loose tip turret base mount, move turn stops to 90 degrees, perform calibration on tip turret, perform park calibration on tip and base turrets, shoot water from pierce tip, operating to specs. Replace two dash switch lamps. Tighten loose sidelight at left rear.

Total for Labor	\$186.24
Total for Parts	\$3,850.98
Total for Work Order #31244	\$4,037.22

WORK ORDER FOR
PIERCING TIP DAMAGE SUSTAINED DURING
ASIANA FLIGHT #214 EVENT.

Mechanic	Date	Approval	Date
----------	------	----------	------